


EAN: 4015474100558
static.hansa.com/43082100

Pièces de rechange

SP43092100



	Nom		Code
1	Levier Chrome Arrêté		43890005
1	Levier Chrome Arrêté		59913774
1	Levier Chrome Arrêté		43880003
1.1	Vis, M5x8, SW2.5		59904755
1.2	Kit de joints pour bec		59904778
1.3	Capuchon Gris		59912112
2	Chape Chrome Arrêté		59912797
3	Vis, M42x1, SW34 Arrêté		59912798
4	Cartouche, 4.0 Classic		59912791
4.1	Temperature adjustment limiter Arrêté		59912799
5.1	Tirette de vidage Chrome		59912804
5.2	Joint		59904624
5.3	Joint, 37x48x3.5		59911422
5.4	Clip plate Arrêté		59912805
5.5	Fixing plate		59904765
5.6	Vis, M8x1, SW13		59904766
5.7	Ensemble de fixation		59910749
5.8	Flexible d'alimentation, L=430, G3/8-M10x1		59912515
5.8	Tuyau de raccordement, L=430, M10x1		59912550
5.9	Joint, 9x2		59905095
5.10	Joint, 9.5x14.4x2		59912551
5.11	Joint, d 7.65x1.78		59902337
5.12	Vis, M8x1, L=140		59912474
6	Aérateur, M24x1 STD HC A Chrome		59902366
6.1	Aérateur, M22/24 A		59902081
7	Vidage Chrome		59911441
N.I.	Rosaces, d 55 mm Chrome		59913471
N.I.	Clef, SW30/34		59912108
N.I.	Bague avec graine d'attache		59902219