


EAN: 4057304020445
static.hansa.com/5447220781

Pièces de rechange

SP54372207CLR



	Nom	Code
01	Écrou de maintien, M34x1.5	1012133V
02	Cartouche, 3.0	1014428V
03	Ensemble de fixation	59913479