

EAN: 4015474202726
static.hansa.com/44509503

Pièces de rechange

SP44509503

	Nom	Code
1	Levier, L=50, M5 IG	59913335
1.1	Vis, M5x35	59913299
1.4	Joint, d 3x1.5	59913100
1.5	Capuchon Chrome	59913332
2	Rosaces, 175x75 mm Chrome Arrêté	59913699
2.1	Chape Chrome	59913364
2.2	Bague glissante	59913363
2.3	Joint, d 38x2	59913212
2.4	Rosace Chrome	59913375
2.7	Support de plaque de couverture	59913697
2.8	Vis, M4x55	59913698
3	Couplage mur Chrome Arrêté	59913700
3.1	Mamelon de fil, G1/2xM18x1	59911384
3.4	Clapet anti-retour	59905714
N.I.	Rallonge pour mitigeur encastrés, 20 mm	59913590

